








KANSAS HIGHWAY SYSTEM District 2

2014 Faulting, Rutting, Cracking


-  Rutting Equal To Or Exceeding 0.3 IN
-  Code 2 and 3 Faulting
-  Crack Candidates



Year of Projects

-  2014 Locations
-  2015 Locations
-  2016 Locations

- 8 Chip Seal
- 12 Overlay 1.5"
- 13 Overlay 3"
- 42 FD PCCP Patching
- 200 New Const (IFD=4)
- 201 New Const (IFD=3)
- 226 SR 2", Chip
- 327 CM .75", HR 1.5"
- 347 CM 2", OV 2"
- 348 UBAS-Novachip
- 351 CM .5", OL 1.5"
- 374 SR 2", UBAS
- 376 CM .5", UBAS
- 385 CM 1", OL 1.5"



prepared by
Kansas Department of Transportation
Bureau of Construction and Materials
based on database snapshot from
August 1, 2014